



Caution

RES3039

Please note this application suffers from steel/dust contamination. This results in failure of the gear mechanism within the starter motor. If the starter motor is renewed without investigating the cause of the dust/debris i.e. careful inspection of the clutch/dual mass flywheel, then failure of the new unit will result, in a very short time

This is not considered a Starter motor fault/warranty failure.

Your warranty will be void if dust contamination is determined to be the cause of failure.



Caution

RES3039

Please note this application suffers from steel/dust contamination. This results in failure of the gear mechanism within the starter motor. If the starter motor is renewed without investigating the cause of the dust/debris i.e. careful inspection of the clutch/dual mass flywheel, then failure of the new unit will result, in a very short time

This is not considered a Starter motor fault/warranty failure.

Your warranty will be void if dust contamination is determined to be the cause of failure.



Caution

RES3039

Please note this application suffers from steel/dust contamination. This results in failure of the gear mechanism within the starter motor. If the starter motor is renewed without investigating the cause of the dust/debris i.e. careful inspection of the clutch/dual mass flywheel, then failure of the new unit will result, in a very short time

This is not considered a Starter motor fault/warranty failure.

Your warranty will be void if dust contamination is determined to be the cause of failure.