



Warning

CU1007

In order to prevent potential further problems with your ignition system, it is strongly recommended that both the ignition leads and spark plugs are changed at the same time that this unit is fitted.



Warning

CU1007

In order to prevent potential further problems with your ignition system, it is strongly recommended that both the ignition leads and spark plugs are changed at the same time that this unit is fitted.



Warning

CU1007

In order to prevent potential further problems with your ignition system, it is strongly recommended that both the ignition leads and spark plugs are changed at the same time that this unit is fitted.



Warning

CU1007

In order to prevent potential further problems with your ignition system, it is strongly recommended that both the ignition leads and spark plugs are changed at the same time that this unit is fitted.