

BMW**3 SERIES E21 — 3 SERIES E36****01527 835555****FuelParts^{UK}**

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
3 SERIES E21													
323i	Saloon		2315	M20			3/78	10/82					FP3004
3 SERIES E30													
316i			1596	M40			9/88	12/90	PABM024				55ltr Tank
316i			1596	M40			9/88	12/90	PABM025				63ltr Tank
316i	Cabrio		1596	M40			1/91	2/94					FP3005
318i	Saloon		1795	M10/ 40			3/83	4/91					FP3005
320i	Cabrio		1991	M20			7/84	1/93		FP2010			FP3005 Replaces Bosch Pump
320i			1991	M20			9/88	4/91		FP2010			FP3005 Replaces Bosch Pump
320i	Saloon		1990	M20			3/83	12/90		FP2010			FP3005 Replaces Bosch Pump
323i	Saloon		2315	M20			3/83	7/85		FP2010			FP3005 Replaces Bosch Pump
325i	Saloon		2316	M20			10/85	5/89		FP2010			FP3005 Replaces Bosch Pump
325i	Cabrio		2494	M20			9/86	11/90		FP2010			FP3005 Replaces Bosch Pump
325i			2494	M20			4/88	12/93		FP2010			FP3005 Replaces Bosch Pump
M3	Saloon		2302	S14			9/86	12/90					FP3005 LHD Only
3 SERIES E36													
316i			1596	M40			4/91	2/94					FP3005
316i	Saloon		1596	M40/ M43			6/91	3/98	PABM017	FP2079B			Replaces Bosch Pump
316i	Coupe		1596	M40/ M43			1/94	3/99	PABM017	FP2079B			Replaces Bosch Pump

FPA3A.503

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
316i Touring Estate		1596		M40/ M43			4/97	8/99	PABM017	FP2079B			Replaces Bosch Pump
316i		1596		M43			9/94	1/99	PABM021	FP2079B			Replaces Bosch Pump
318i OHC Cabrio		1796		M43			5/95	12/99		FP2079B			Replaces Bosch Pump
318i OHC Saloon		1795		M40/ M43			4/91	4/98		FP2079B			Replaces Bosch Pump
318i Touring OHC Estate		1796		M43			1/96	8/99		FP2079B			Replaces Bosch Pump
318i Compact Hatch		1895		M44			9/94	4/96	PABM021				
318iS Coupe		1895		M42			4/92	4/96		FP2079B			Replaces Bosch Pump
318iS Coupe		1895		M44			4/92	4/96		FP2079B			Replaces Bosch Pump
318i Coupe		1895		M44			4/96	3/99	PABM017	FP2079B			Replaces Bosch Pump
318i Compact Hatch		1895		M44			4/96	1/01	PABM021				
320i Saloon		1991		M50			4/91	9/96	PABM017	FP2079B			Replaces Bosch Pump
320i Cabrio		1991		M52			5/94	12/97	PABM017	FP2079B			Replaces Bosch Pump
320i Coupe		1991		M50			4/92	9/95	PABM017	FP2079B			Replaces Bosch Pump
320i Touring		1991		M52			3/95	12/97	PABM017	FP2079B			Replaces Bosch Pump
323i Saloon		2494		M52			9/96	5/98	PABM017	FP2079B			Replaces Bosch Pump
323i Coupe		2494		M52			3/95	3/99	PABM017	FP2079B			Replaces Bosch Pump
323i Touring		2494		M52			1/97	8/99	PABM017	FP2079B			Replaces Bosch Pump

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
325i Saloon		2494		M50			4/91	9/95	PABM017	FP2079B			Replaces Bosch Pump
325i Cabrio		2494		M50			7/93	9/95	PABM017	FP2079B			Replaces Bosch Pump
325i Coupe		2494		M50			4/92	9/95	PABM017	FP2079B			Replaces Bosch Pump
328i Saloon		2793		M52			3/95	3/98	PABM017	FP2079B			Replaces Bosch Pump
328i Cabrio		2793		M52			3/95	12/99	PABM017	FP2079B			Replaces Bosch Pump
328i Coupe		2793		M52			3/95	3/99	PABM017	FP2079B			Replaces Bosch Pump
328i Touring		2793		M52			3/95	8/99	PABM017	FP2079B			Replaces Bosch Pump
318 TDS Saloon		1665		M41			8/95	3/98	PABM018				
318 TDS Touring		1665		M41			1/95	2/98	PABM018				
318 TDS Compact Hatch		1665		M41			1/95	8/00	PABM019				
325TDS Saloon		2498		M51			7/93	3/98	PABM018				
325TDS Touring		2498		M51			1/96	8/99	PABM018				
M3		2990		S50B30			10/92	10/95	PABM017	FP2079B			
M3 Evolution		3201		S50B32			10/95	4/99	PABM017	FP2079B			
3 SERIES E46													
316i Compact Hatch		1796		M43			8/01		PABM022				
316i Saloon		1796		M43			1/02		PABM022				
316i Touring		1796		M43			3/02		PABM022				

BMW**3 SERIES E46 Cont. — 3 SERIES E46****01527 835555****FuelParts^{UK}**

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
318i Saloon		1895		M44			2/98	1/99	PABM017	FP2079B			Replaces Bosch Pump
318i Cabrio		1796		M43			10/99	8/01	PABM022				
318i Saloon		1895		M43			9/98	12/01	PABM022				
318i Touring		1895		M43			9/99	9/01	PABM022				
320i Ci Cabrio		2171		M54			9/00		PABM022				
320i Ci Coupe		2171		M54			9/00		PABM022				
320i Saloon		2171		M54			9/00		PABM022				
320i Touring		2171		M54			9/00		PABM022				
323i Cabrio		2494		M52			1/97	5/00		FP2079B			Replaces Bosch Pump
323i Saloon		2494		M52			12/98	7/00	PABM022				
323i Ci Cabrio		2494		M54			5/00	7/00	PABM022				
323i Ci Coupe		2494		M52			3/99	7/00	PABM022				
325i Ci Cabrio, Coupe		2494		M54			9/00		PABM022				
325i Saloon, Touring		2494		M54			9/00		PABM022				
328i Ci Coupe		2793		M52			3/99	6/00	PABM022				
328i Saloon		2793		M52			9/99	6/00	PABM022				
328i SE Touring		2793		M52			9/98	6/00	PABM022				

FPA3A.503.

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
330 Ci	Cabrio, Coupe		2979	M54			7/00		PABM022				
330 i	Saloon, Estate		2979	M54			7/00		PABM022				
320 D	Saloon		1951	M47			10/99 - 8/01		PABM020				
320 D	Touring		1951	M47			9/99 - 8/01		PABM020				
5 SERIES E12													
528i	Saloon		2788	M30			9/77 - 10/81					FP3005	
5 SERIES E28													
518i	Saloon		1766	M10			1/85 - 12/87					FP3005	
520i	Saloon		1990	M20			10/81 - 12/87					FP3005	
525i	Saloon		2494	M30			10/81 - 10/87					FP3005	
525i	Saloon		2494	M20			6/83 - 12/87					FP3005	
528i	Saloon		2788	M30			10/81 - 11/87					FP3005	
535i	Saloon		3430	M30			1/85 - 11/87					FP3005	
M5			3453	S35			7/86 - 11/87					FP3005	
5 SERIES E34													
518i	Saloon		1796	M43			1/90 - 3/96			FP2077B			Metal Fuel Tank - Replaces Bosch Pump
518i	Saloon		1796	M43			1/90 - 3/96			FP2096B			Plastic Fuel Tank-replaces Bosch Pump
518i	Touring		1796	M43			5/94 - 9/96			FP2077B			Metal Fuel Tank-replaces Bosch Pump

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
518i Touring		1796		M43			5/94	9/96		FP2096B			Plastic Fuel Tank-replaces Bosch Pump
520i Saloon		1991		M20			6/88	9/90		FP2077B			Replaces Bosch Pump
520i 24v Saloon		1991		M50			9/90	3/96		FP2077B			Metal Fuel Tank-replaces Bosch Pump
520i 24v Saloon		1991		M50			9/90	3/96		FP2096B			Plastic Fuel Tank-replaces Bosch Pump
520i Touring 24v		1991		M50			3/92	9/96		FP2077B			Metal Fuel Tank-replaces Bosch Pump
520i Touring 24v		1991		M50			3/92	9/96		FP2096B			Metal Fuel Tank-replaces Bosch Pump
525i 12v Saloon		2494		M20			6/88	9/90		FP2077B			Replaces Bosch Pump
525i 24v Saloon		2494		M50			9/90	3/96		FP2077B			Metal Fuel Tank-replaces Bosch Pump
525i 24v Saloon		2494		M50			9/90	3/96		FP2096B			Plastic Fuel Tank-replaces Bosch Pump
525i Touring 24v		2494		M50			3/92	9/96		FP2077B			Metal Fuel Tank-replaces Bosch Pump
525i Touring 24v		2494		M50			3/92	9/96		FP2096B			Plastic Fuel Tank-replaces Bosch Pump
525i X Touring 4x4		2494		M50			7/92	9/96		FP2077B			(4x4)-replaces Bosch Pump
530i 6 Cyl Eng Saloon		2986		M30			6/88	7/90		FP2077B			Replaces Bosch Pump
530i V8 Saloon		2997		M60			1/93	3/96		FP2077B			Metal Fuel Tank-replaces Bosch Pump

BMW**5 SERIES E34 Cont. — 6 SERIES E24****01527 835555****FuelParts^{UK}**

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
530i V8 Saloon		2997		M60			1/93	3/96		FP2062			Plastic Fuel Tank-replaces VDO Pump
530i Touring V8		2997		M60			1/93	9/96		FP2077B			Metal Fuel Tank-replaces Bosch Pump
530i Touring V8		2997		M60			1/93	9/96		FP2062			Plastic Fuel Tanks-replaces VDO Pump
535i Saloon		3430		M30			6/88	12/92		FP2077B			Replaces Bosch Pump
540i V8 Saloon		3982		M60			1/93	3/96		FP2077B			Replaces Bosch Pump
540i Touring V8		3982		M60			5/94	9/96		FP2077B			Replaces Bosch Pump
M5		3535		S36			2/90	11/91		FP2077B			
M5		3795		S38			2/92	9/95		FP2077B			
525TD Saloon, Touring		2498		M51			7/93	9/96			SP2006		
525TD Saloon, Touring		2498		M51			7/93	9/96			SP2006		
5 SERIES E39													
525 D Saloon		2497		M51			9/00					FP3013	
525 D Touring		2497		M51			9/00					FP3013	
530 D Saloon		2993		M57			9/98	12/03				FP3013	
530 D Saloon		2993		M57			9/98	12/03				FP3013	
6 SERIES E24													
628 CSi Coupe		2788		M30			9/80	5/87				FP3005	

FPA3A.503



6 SERIES E24 Cont. — Z1

01527 835555



Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
635 CSi Coupe		3453		M30			10/78	6/82		FP2010		FP3005	Replaces Bosch Pump
635 CSi Coupe		3430		M30			9/85	9/89				FP3005	
635 CSi Coupe		3430		M30			8/87	9/89		FP2010		FP3005	Replaces Bosch Pump
7 SERIES E23													
728i Saloon		2788		M30			76	5/86				FP3005	
7 SERIES E32													
730i 6cyl Eng Saloon		2997		M30			5/87	8/94		FP2077B			Replaces Bosch Pump
730i V8 Saloon		2997		M60			9/92	8/94		FP2077B			Replaces Bosch Pump
735i Saloon		3430		M30			2/87	5/92		FP2077B			Replaces Bosch Pump
740i Saloon		3982		M60			9/92	8/94		FP2077B			Replaces Bosch Pump
7 SERIES E38													
730i V8 Saloon		2997		M60			8/94	9/01		FP2062			Replaces VDO Pump
X5 E53													
3.0i Turbo Diesel Sports Utility Vehicle		2926		M57			3/01					FP3013	
Z1													
2.5i		2316		M20			10/89	6/91				FP3005	