

CITROEN

AX — BX

01527 835555

FuelParts^{UK}

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
AX													
1.0i			954 cc	TU9/ TU9M		[ZALH/ ZALJ]	8/92	4/97		FP2029		FP3003	Replaces Bosch Pump
1.1i			1124 cc	TU1M		[ZADA/ ZADB]	9/91	4/92		FP2029			Replaces Bosch Pump
1.1i			1124 cc	TU1M		[ZADA/ ZADB]	5/92	4/96		FP2035			Replaces Walbro Pump
1.4i			1360 cc	TU3M			7/87	6/90		FP2029			Replaces Bosch Pump
1.4i			1360 cc	TU3FJ2			9/92	6/95		FP2034			Replaces Bosch Pump
BERLINGO													
1.4i Multispace OHC MPV			1360 cc	TU3JP			4/99	6/00	PACT038				
1.4i Multispace OHC MPV			1360 cc	TU3JP			7/00	->	PACT025				
1.6i Multispace DOHC 16v MPV			1587 cc	TU3JP4			11/00	->	PACT025				
1.8i Multispace OHC MPV			1761 cc	XU7JB			6/98	10/00	PACT038				
2.0i Multispace MPV			1997 cc	DW10TD			1/02	->	PACT041				
BX													
1.4 Hatch			1360 cc	150C		[XB]	8/83	10/91				FP3021	
1.4i			1360 cc	150C		[XB]	8/83	10/91		FP2056			Replaces Bosch Pump
1.6 Hatch			1580 cc	180Z		[XB]	3/87	5/93				FP3005	
1.6 Estate			1580 cc	180Z		[XB]	8/85	6/94				FP3005	
1.9i Hatch			1905 cc	XU92C		[XB]	6/86	5/93				FP3005	
1.9i Estate			1905 cc	XU92C		[XB]	4/88	2/92				FP3005	

CITROEN

C3 — CX

01527 835555

FuelParts^{UK}

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
C3													
1.1i			1124 cc	TU1JP			4/02	->	PACT043				
1.4i			1360 cc	TU3JP			4/02	->	PACT043				
1.6i 16v			1587 cc	TU5JP4			4/02	->	PACT043				
1.4		70	1398 cc	DV4TD			1/02	->	PACT043				
1.4		92	1398 cc	DV4TED4			1/02	->	PACT043				
C5													
1.8i 16v Hatch			1749 cc	EW754			4/01	->	PACT042				
1.8i 16v Estate			1749 cc	EW754			6/01	->	PACT042				
2.0i Hatch			1997 cc	EW1054			4/01	->	PACT042				
2.0i Estate			1997 cc	EW1054			4/01	->	PACT042				
2.0i 16v Hatch			1997 cc	EW10D			3/01	->	PACT051				
2.0i 16v Estate			1997 cc	EW10D			3/01	->	PACT051				
3.0i V6 Hatch			2946 cc	ES954S			4/01	->	PACT042				
3.0i V6 Estate			2946 cc	ES954S			6/01	->	PACT042				
CX													
2.0 Carb			1995 cc	829A5			8/79	- 9/85					FP3022
2.4 Carb Saloon			2347 cc	M23-623			8/79	- 1/81					FP3005
2.4i Saloon			2347 cc	M23-622			1/78	- 8/83					FP3005

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
2.4 Estate			2347 cc	M23-623			8/76	9/82				FP3005	
2.4i Estate			2347 cc	M23-622			1/82	9/82				FP3005	
2.5i			2500 cc	M25-668			7/89	11/89				FP3005	
2.5i Turbo			2500 cc	M25-662			9/84	11/89				FP3005	
SAXO													
1.0i			954 cc	TU9M		[SOCDZE/ SOCDZF/ S1CDZE/ S1CDZF]	5/96	12/97	PACT026	FP2029			Replaces Bosch Pump
1.0i			954 cc	TU9M		[SOCDZE/ SOCDZF/ S1CDZE/ S1CDZF]	1/98	->	PACT027	FP2029			Replaces VDO Pump
1.0i			954 cc	TU9M		[SOCDZE/ SOCDZF/ S1CDZE/ S1CDZF]	1/98	->	PACT028				
1.1i			1124 cc	HFX		[SOHDZE/ SOHDZF/ S1HDZE/ S1HDZF]	10/99	->	PACT040				
1.1i			1124 cc	TU1M		[SOHDZE/ SOHDZF/ S1HDZE/ S1HDZF]	5/96	12/97	PACT026	FP2029			Replaces Bosch Pump
1.1i			1124 cc	HDZ		[SOHDZE/ SOHDZF/ S1HDZE/ S1HDZF]	1/98	->	PACT027	FP2029			Replaces Bosch Pump
1.4i			1360 cc	TU3J		[SOKFXF/ SOKFXD/ S1KFXD/ S1KFXF]	5/96	->	PACT028	FP2034			Replaces VDO Pump
1.4i			1360 cc	TU3J		[SOKFXF/ SOKFXD/ S1KFXD/ S1KFXF]	4/91	3/96	PACT026				
1.6i OHC			1587 cc	TU5JP4		[SONFZF/ SONFZD/ S1NFZD]	10/96	12/97	PACT028				Replaces VDO Pump
1.6i 16v			1587 cc	TU5JP4			1/97	9/99	PACT028				Replaces VDO Pump

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
1.6i			1587 cc	TU5JP		[SONFZF/ SONFZD/ S1NFZD]	10/99 ->		PACT044				With VDO Pump
1.6i Vtr OHC			1587 cc	TU5JP		[SONFZF/ SONFZD/ S1NFZD]	10/96 - 12/97		PACT029				Replaces Bosch Pump
1.6i Vtr 16v			1587 cc	TU5JP			1/97 - 9/99		PACT029				Replaces Bosch Pump
1.6i Vtr 16v			1587 cc	TU5JP			10/99 ->		FP5014				Replaces VDO Pump
SYNERGIE													
2.0i			1998 cc	XU10J21C	CH7846	[U6UB]	10/95 - 5/98		PACT032				Without Trip Computer
2.0i			1998 cc	XU10J21C	CH7846	[U6UB]	10/95 - 5/98		PACT030				With Trip Computer
2.0i			1998 cc	XU10J4R			6/98 ->		PACT031				
VISA													
1.6i GTi			1580 cc	XU5J			7/85 - 6/87					FP3005	
XANTIA													
1.6i			1580 cc	XU5JP		[X12B]	7/93 - 5/97		PACT033	FP2056			Replaces Bosch Pump
1.8i OHC Hatch			1761 cc	XU7JB		[X11A/ X17A/ X19B]	7/93 - 1/98		PACT033	FP2056			Replaces Bosch Pump
1.8i OHC Estate			1761 cc	XU7JB		[11E/ X12E]	9/95 - 11/97		PACT031	FP2056			Replaces Bosch Pump
1.8i OHC Hatch			1761 cc	XU7JB		[X11A/ X17A/ X19B]	1/98 - 1/99		PACT031	FP2056			Replaces Bosch Pump
1.8i 16v			1761 cc				7/93 - 1/99			FP2057			Replaces Walbro Pump
1.8i DOHC Hatch			1761 cc	UX7JP4			1/98 - 4/01		PACT033	FP2056			Replaces Bosch Pump
2.0i OHC Hatch			1998 cc	XU10J21C			7/93 - 5/97		PACT033	FP2056			Replaces Bosch Pump

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
2.0i 16v			1998 cc				7/93	1/99		FP2057			Replaces Walbro Pump
2.0i OHC Estate			1998 cc	XU10J21C		[X1RFXM/ X14A/ X14C/ X17B/ X13E/ X2RFVF/ X2RFVM]	9/95	5/97	PACT033	FP2056			Replaces Bosch Pump
2.0i DOHC Estate			1998 cc	XU10J4R			9/95	10/00	PACT034	FP2056			Replaces Bosch Pump
2.0i DOHC Hatch			1998 cc	XU10J412			5/97	10/00	PACT034	FP2056			Replaces Bosch Pump
2.0i Turbo Hatch			1998 cc	XU10J2TE			2/96	10/00	PACT034	FP2056			Replaces Bosch Pump
2.0i			1997 cc			[X1RHZF/ X7RHZF]	6/99	10/00	PACT045				
XM													
2.0i			1998 cc	XU10MZ		[Y3AC/ Y3AR/ Y3AP]	11/91	7/94				FP3005	
2.0i Turbo			1998 cc	XU10J2TE		[Y4GG/ Y4TT]	1/93	10/00				FP3005	
2.0i DOHC 16v			1998 cc	XU10J4R		[Y4GG/ Y4TT]	7/94	6/99				FP3005	
3.0i V6			2975 cc	ZPJ/ 2		[Y3AC/ Y43AR/ Y3AP]	11/91	7/94		FP2056			Replaces Bosch Pump
3.0i V6			2963 cc	ZPJ/ 2		[Y4GG/ Y4TT]	7/94	10/00		FP2056			Replaces Bosch Pump
XSARA													
1.4i Hatch			1360 cc	TU3JP		[NOKFXF/ N1KFXF/ N2KFXF]	11/97	->	PACT035				
1.4i Estate			1360 cc	TU3JP		[NOKFXF/ N1KFXF/ N2KFXF]	5/98	12/01	PACT035				
1.6i OHC Hatch			1587 cc	TU5JP			11/97	11/00	PACT035				
1.6i OHC Estate			1587 cc	TU5JP			5/98	10/00	PACT035				

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
1.6i 16v Hatch			1587 cc	TU5JP4			10/00	->	PACT035				
1.6i 16v Estate			1587 cc	TU5JP4			1/00	->	PACT035				
1.8i OHC Hatch			1761 cc	XU7JB			11/97	- 6/99	PACT035				
1.8i 16v Hatch			1761 cc	XU7JP4			11/97	- 10/00	PACT035				
1.8i OHC Estate			1761 cc	XU7JB			5/98	- 6/99	PACT035				
1.8i 16v Estate			1761 cc	XU7JP4			5/98	- 8/00	PACT035				
2.0i 16v			1998 cc	XU10J4R			3/98	->	PACT035				
2.0i Hatch		90	1997 cc	DW10TD		[N2RHYF]	6/99	- 12/01	PACT039				
2.0i Estate		90	1997 cc	DW10TD		[N2RHYF]	6/99	- 12/01	PACT039				
2.0i Hatch		110	1997 cc	DW10ATED		[N2RHYF]	5/01	->	PACT039				
2.0i Estate		110	1997 cc	DW10ATED		[N2RHYF]	5/01	->	PACT039				
1.6i Picasso MPV			1587 cc				6/00	->	PACT040				
1.8i Picasso MPV			1749 cc	EW754			6/00	->	PACT040				
1.8i Picasso MPV			1762 cc	XU7JP4			6/00	->	PACT040				
2.0 Picasso HDi MPV			1997 cc	DW10TD			6/00	- 8/00	PACT039				
2.0i Picasso MPV			1997 cc	DW10TD			9/00	->	PACT041				

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
ZX													
1.4i			1360 cc	TU3M12		[N2A9/ N2B1/ N2L7/ N2L9/ N2D]	5/96	6/97	PACT036	FP2061			Replaces Bosch Pump
1.4i			1360 cc	TU3M12		[N2A9/ N2B1/ N2L7/ N2L9/ N2D]	5/96	6/97		FP2122			Replaces VDO Pump
1.6i			1580 cc	XU5M/ XU5JP			6/91	10/96		FP2061			Replaces Bosch Pump
1.6i			1580 cc	XU5M/ XU5JP			6/91	5/96		FP2004			Replaces Walbro Pump
1.8i			1761 cc	XU7JP			10/92	10/96		FP2058			Replaces Bosch Pump
1.9i			1905 cc	XU9JA			1/92	6/95	PACT037	FP2058			Replaces Bosch Pump
2.0i 8v			1998 cc	XU10J2C			10/92	6/96		FP2058			Replaces Bosch Pump
2.0i 16v			1998 cc	XU10J4/ Z			10/92	6/96		FP2058			Replaces Bosch Pump