

HONDA

ACCORD — CR-V

01527 835555



Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
ACCORD													
	2.0i ES, LS		1997	F20Z2			4/93	95		FP2005			Replaces Nippon Denso Pump
	2.2i ES		2156	F22A3			11/89	95		FP2005			Replaces Nippon Denso Pump
	2.3i SR		2259	H23A3			4/93	95		FP2005			Replaces Nippon Denso Pump
CIVIC													
	1.5i		1493	D15B2/ D15Z1		[EG, EH]	11/91	3/96		FP2005			Replaces Nippon Denso Pump
	1.5i		1493	DB15Z6		[EJ, MB]	6/95	3/01		FP2063B			
	1.6i V-tec		1590	D16YS		[EJ, MB]	6/95	3/01		FP2063B			
CR-V													
	2.0i		1973	B20B		[RD1, RD3]	6/97	3/99		FP2005B			