

# MAZDA

## 323 — RX7

### 01527 835555

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
<b>323</b>													
	1.6i Hatch		1598	B6			5/91	6/94		FP2007			Replaces Nippon Denso Pump
<b>626</b>													
	1.8i Saloon, Hatch		1789				1/90	10/99		FP2025			Replaces Nippon Denso Pump
	2.0i Hatch		1991	F5			2/92	9/97		FP5005			
	2.5i Hatch		2497	KL			2/92	12/94		FP2025			Replaces Nippon Denso Pump
<b>MX3</b>													
	1.6i 16v	88	1598	B69			9/91	4/94		FP2041			Replaces Nippon Denso Pump
	1.8i V6	134	1845	K838			9/91	8/94		FP2041			Replaces Nippon Denso Pump
<b>MX5</b>													
	1.6i Cabrio		1598	B64F			5/94	4/98		FP2041		FP3026	Replaces Nippon Denso Pump
	1.8i Cabrio		1839	BPF1			1/90	4/98		FP2041		FP3026	Replaces Nippon Denso Pump
	1.8i Cabrio		1839	BP-ZE			4/98			FP2041		FP3026	Replaces Nippon Denso Pump
<b>RX7</b>													
	2.6i Turbo		2616	RE13B			6/92	10/95		FP2042			Replaces Nippon Denso Pump

FPA3A.503.

# MAZDA

XEDOS — XEDOS

01527 835555

FuelParts<sup>UK</sup>

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
<b>XEDOS</b>													
1.6i 6		1598		B6			10/93	7/97		FP2025			Replaces Nippon Denso Pump
2.0i 6 V6		1995		KF1			6/92	6/98		FP2025			Replaces Nippon Denso Pump
2.5i 9 V6		2497		KJ-2EM			1/94	10/98		FP2025			Replaces Nippon Denso Pump