

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
ESPERO													
1.5i 16v			1498	A15MF			4/95	10/96		FP2009			Replaces Walbro Pump / Will Not Replace AC Type
1.8i 8v			1796	C18LE			4/95	9/97		FP2009			Replaces Walbro Pump / Will Not Replace AC Type
2.0i 8v			1998	C20LE			5/94	10/97	PADA043	FP2009			Replaces Walbro Pump / Will Not Replace AC Type
LANOS													
1.4i			1349	A14SMS			9/97		PADA040				With Walbro Or VDO Pump
1.6i 16v			1598	A16DMS			9/97	7/02	PADA040	FP2093B			
MATIZ													
800i			796				8/98		PAPA041	FP2093B			
NEXIA													
1.5i 8v			1498	G15MF			4/95	10/97		FP2009			Replaces Walbro Pump / Will Not Replace AC Type
1.5i 16v			1498	A15MF			4/95	10/97		FP2110			Replaces Walbro Pump / Will Not Replace AC Type

DAEWOO

NUBIRA — NUBIRA

01527 835555



Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes	
NUBIRA														
1.6i 16v		1598		A16DMS			9/97	6/02	PADA042	FP2093B				
2.0i 16v		1998		X20SED			9/97	6/02	PADA042	FP2093B				