

FIAT

BARCETTA — BRAVA

01527 835555

FuelParts^{UK}

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
BARCETTA													
1.8i 16v		1747		183A1.000/ 188A6.000	Ch ->37640		9/95	5/98	PAFT044				Excludes Orange Colour Coded Pump
1.8i 16v		1747		183A1.000/ 188A6.000	Ch ->37640		9/95	5/98	PAFT043				With Orange Colour Coded Pump
1.8i 16v		1747		183A1.000/ 188A6.000	Ch 37641->		6/98		PAFT046				
1.8i 16v		1747		183A1.000/ 188A6.000			9/95			FP2057			Replaces Walbro Pump / Will Not Replace AC
BRAVA													
1.2i 16v		1242		188A5.000			2/99	12/01	PAFT079				
1.4i 12v		1370		182A3.000			7/96	2/99	PAFT050				
1.4i 12v		1370		182A3.000			7/96	2/99		FP2018B			
1.6i 16v		1581		182A6.000			7/96	4/98	PAFT047	FP2057			
1.6i 16v		1581		182A6.000			5/98	12/01	PAFT048				Without Return
1.6i 16v		1581		182A6.000			7/96	10/00		FP2057			
1.6i 16v		1581		182A6.000			10/00		PAFT072				(Euro3)
1.8i 16v		1747		182A2.000			12/95	6/99		FP2057			
1.8i 16v		1747		182A2.000			7/96	6/99	PAFT045				
1.8i 16v		1747		182A2.000			7/99	3/01	PAFT052				

FIAT

BRAVO — COUPE

01527 835555

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
BRAVO													
1.9i		1910		182A7.000			12/00		PAFT075				
1.2i 16v		1242		188A5.000/ 182B2.000			2/99 - 12/01		PAFT079				
1.4i 12v		1370		182A3.000			7/96 - 2/99			FP2018B			
1.6i 16v		1581		182A6.000			7/96 - 4/98			FP2057			
1.6i 16v		1581		182A4.000			5/98 - 9/00			FP2087B			
1.6i 16v		1596		182A4.000			10/00		PAFT072				(Euro3)
1.8i 16v		1747		182A2.000			12/95 - 6/99		PAFT045				
1.8i 16v		1747		182A2.000			12/95 - 6/99			FP2057			
CINQUECENTO													
900i		903		170A1.000			5/93			FP2018			Replaces Bosch / Weber Pump
1.1i Sporting		1108		176B2.000			5/93 - 6/98			FP2018			Replaces Bosch / Weber Pump
COUPE													
2.0i 16v		1995		836A3.000			6/95 - 10/96			FP2063			
2.0i 16v		1995		836A3.000			6/95 - 10/96		PAFT049				
2.0i 20v		1998		182A1.000			11/96 - 4/98		PAFT055				
2.0i 20v		1998		182A1.000			11/96 - 4/98			FP2063			
2.0i 20v		1998		182A1.000/ 182B3.000			4/98 - 2/00		PAFT049				
2.0i Turbo 16v		1995		836A3.000			6/95 - 10/96			FP2057			Replaces Walbro Pump

FPA3A.503.

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
	2.0i Turbo 20v		1998	175A3.000			11/96	10/98	PAFT054				
	2.0i Turbo 20v		1998	175A3.000			11/96	10/98		FP2063			
	2.0i Turbo 20v		1998	175A3.000			10/98		PAFT056				
	2.0i Turbo 20v		1998	175A3.000			10/98			FP2063			
CROMA													
	2.0i		1998				6/86	5/92		FP2090B			
MAREA													
	1.6i 16v		1581	182A4.000			3/97	4/98		FP2057			Replaces Bosch Pump
	1.6i 16v		1581	182A4.000			3/97	10/99	PAFT045				
	1.6i 16v		1581	182A4.000			11/99	9/00	PAFT073				
	1.6i 16v		1581	182A4.000			10/00	4/02	PAFT072				
	1.8i 16v		1747	182A2.000			3/97	6/99		FP2057			
	1.8i 16v		1747	182A2.000			3/97	6/99	PAFT045				
	1.8i 16v		1747	182A2.000			7/99	12/00	PAFT073				
	2.0i 20v		1988	182A1.000			3/97	5/99		FP2063			Replaces Walbro Pump
	2.0i 20v		1998	182A1.000			3/97	5/99	PAFT049				
	2.0i 20v		1998	185A8.000			5/99	4/02	PAFT079				
	1.9		1910				3/99	12/00	PAFT053				

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
1.9		1910		186A6.000			12/00	4/02	PAFT075				
2.4 130		2387		839A5.000			3/99	12/00	PAFT053				
MULTIPLA													
1.6i MPV		1581		186A3.000			1/00		PAFT058				
1.9 TD MPV		1910		182B4.000/ 186A6.000			12/99		PAFT074				
1.9 MPV		1910		186A6.000			1/00		PAFT060				
PANDA													
900i		903		100GL3.000			1/92	8/92		FP2037			Replaces Walbro Pump
1.0i		999		146A.000			4/86	1/92		FP2018			Replaces Bosch / Weber Pump
1.0		999		153A2.246/ 141C2.000			1/92	6/95		FP2018			Replaces Bosch / Weber Pump
PUNTO													
1.1i 55		1108		176A6.000/ 176B2.000			3/94	5/97		FP2037			Replaces Walbro Pump
1.1 55		1108		176B2.000			3/94	5/97	PAFT061	FP2037			
1.2i 60 OHC		1242		176A7.000			8/94	9/99	PAFT061				
1.2i 75 OHC		1242		176A7.000			5/94	3/98		FP2057			Replaces Walbro Pump
1.2i 75 OHC		1242		176A7.000			5/94	1/98	PAFT044				
1.2i 85 DOHC		1242		176B9.000			5/97	9/99	PAFT044				
1.2i 75 OHC		1242		176A8.000			1/98	3/98	PAFT046				
1.2i OHC 8v		1242		188A4.000			10/99		PAFT064				

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
1.2i DOHC 16v		1242		188A5.000			10/99		PAFT046				
1.4i GT Turbo		1372		176A4.000/ 176B6.000			3/94 - 9/99		PAFT062	FP2056			Replaces Bosch Pump
1.6 90		1581		176A9.000			8/94 - 5/97		PAFT044	FP2057			
1.8 16v		1747		183A1.000/ 188A6.000			10/99		PAFT065				
1.9 Turbo Diesel		1910		188A2.000			10/99		PAFT066				
SEICENTO													
900i		899		170A1.046			6/98 - 10/00		PAFT067				
1.1i		1108		176B2.000			6/98 - 6/00		PAFT067				
1.1i		1108		176B2.000			7/00		PAFT068				
STILO													
1.2i		1242		188A5.000			2/02		PAFT080				
1.6i		1596		182B6.000			2/02		PAFT080				
1.8i		1747		192A4.000			2/02		PAFT080				
1.9 Turbo Diesel		1910		192A3.000			2/02		PAFT083				
2.4i		2446		192A2.000			2/02		PAFT080				
TIPO													
1.4i		1372		160A1.000/ A160A1.048		[160]	4/90 - 10/95			FP2018			Replaces Bosch / Weber Pump
1.6i		1581		160A2.000		[160]	4/90 - 7/92			FP2018			Replaces Bosch / Weber Pump
1.8i		1756				[160]	1/92 - 7/93			FP2014			Replaces Bosch / Weber Pump

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
2.0i 8v			1995			[160]	6/93	10/95		FP2014			Replaces Bosch / Weber Pump
2.0i 16v			1995			[160]	6/93	10/95		FP2057			Replaces Walbro Pump
2.0i 16v			1995			[160]	6/93	10/95		FP2014			Replaces Bosch Pump
ULYSSE													
2.0i 8v			1998	XU10J2C			10/95	5/98		FP2057			Replaces Walbro Pump
2.0i 8v			1998	XU10J2C			10/95	5/98	PAFT069				
2.0i 16v			1998	RFV			10/95	5/98		FP2057			Replaces Walbro Pump
2.0i 16v			1998	RFV			10/95	5/98	PAFT070	FP2057			
2.0i 16v			1998	RFV			6/98		PAFT050				
UNO													
900 Carb			903	146A.000/ 146A1.000			1/86	1/93		FP2018			
1.0 Carb			999				1/86	7/92		FP2018			
1.0 45			999	156A2.246			1/90	7/95	PAFT071	FP2020			
1.0i 45			999				2/93	6/95		FP2018			Replaces Bosch Pump
1.0i			999				2/93	6/95		FP2020			Replaces Walbro Pump
1.1i 60			1108				1/90	2/94	PAFT071	FP2020			
1.3 Turbo			1301	146A2.146			7/85	1/90				FP3007	
1.4i 70			1372	160A1.046			1/90	9/94	PAFT071	FP2018			Replaces Bosch / Weber Pump