

# HYUNDAI

## ACCENT — SONATA

### 01527 835555



Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
<b>ACCENT</b>													
1.3i			1341	G4EH			10/94	5/99		FP2005B			
1.3i			1341	G4EH			6/99			FP2089B			
1.5i 12v			1495	G4EK			10/94	5/99		FP2005B			
1.5i 12v			1495	G4EB			6/99			FP2089B			
1.5i 16v			1495	G4EK			10/94	5/99		FP2005B			
1.5i 16v			1495	G4EC-G			6/99			FP2089B			
<b>COUPE</b>													
1.6i			1599				6/97	1/00		FP2005B			
2.0i			1975	G4GF			6/97	1/00		FP2005B			
<b>LANTRA</b>													
1.5i			1468	G15B/ G4DJ			10/93	7/95		FP2011			Replaces Walbro Pump
1.6i			1596	G4CR			6/91	10/95		FP2021			Replaces Nippon Denso Pump
1.8i			1836	G4CN			9/92	7/95		FP2021			Replaces Nippon Denso Pump
<b>S COUPE</b>													
1.5i			1495				10/92	8/93		FP2091			
<b>SONATA</b>													
1.8i			1795				6/89	6/92		FP2023			Replaces Walbro Pump
2.0i			1997				6/89	6/92		FP2021			Replaces Nippon Denso Pump

# HYUNDAI

SONATA Cont. — PONY

01527 835555



Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
2.0i			1997				6/89	6/92		FP2023			Replaces Walbro Pump
3.0i V6			2972	G6AT			10/94	8/98		FP2021			Replaces Nippon Denso Pump
<b>PONY</b>													
1.3i			1298				10/92	10/94		FP2005B			
1.5i			1468	G15B/ G4DJ			8/88	10/90		FP2011			