

ROVER

MAESTRO — SD1

01527 835555

FuelParts^{UK}

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
MAESTRO													
2.0i Efi		1994					10/84	11/91				FP3005	
METRO													
1.1i 8v		1119		11K2A			9/92	1/95		FP2050			Replaces AC Pump
1.3i MG Turbo		1275					10/82	9/89				FP3005	
1.4i 8v		1396		14K2A/ 14K2D			5/92	1/95		FP2050			Replaces AC Pump
1.4i 8v		1396					5/92	1/95		FP2051			Replaces AC Pump
1.4i 16v		1396					5/92	1/95		FP2050			Replaces AC Pump
1.4i 16v		1396		14K4F			5/92	1/95		FP2051			Replaces AC Pump
MONTEGO													
2.0i Efi Mayfair		1994		20H			2/86	10/88				FP3005	
2.0i Hli Estate		1994		20H			4/87	10/88				FP3005	
2.0i MG Turbo		1994					4/85	8/88				FP3005	
MINI													
1.3i		1274		12A2L			5/92	9/96	PARO114				
1.3i		1274		12A2L			10/96	12/02		FP2050			Replaces AC Pump
1.3i		1274		12A2L			10/96	12/02	PARO115				
SD1													
3.5 Vitesse Carb		3528		30A/ 31A			10/82	10/86				FP3006	
3.5i V8 S		3528					10/82	10/86				FP3005	

ROVER

100 — 200

01527 835555

FuelParts^{UK}

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
100													
	1.1i 111 Hatch		1119	11K2A/ 11K2D			1/95	4/96		FP2018B			
	1.4i 114 Hatch		1396	14K2A/ 14K2D			1/95	4/96		FP2018B			
200													
	1.1i 211		1120				1/98	10/99	PARO110				
	1.4 214 DOHC Hatch		1396				10/89	11/95	PARO112				
	1.4i 214		1396		Ch 605482->		10/92	2/96	PARO111	FP2109			
	1.4i 214 DOHC Cabrio		1396		Ch 605482->		4/92	12/95	PARO112				Without Level Sensor
	1.4i 214		1396		Ch 605482->		4/93	3/96	PARO112				Without Level Sensor
	1.4i 214 OHC		1396	14K2F			11/95	10/99	PARO110				
	1.4i 214 DOHC		1396	14K4F			11/95	6/99	PARO110				
	1.6 216 Carb		1598	16H			3/85	9/90				FP3006	
	1.6i 216		1589	16K4F			11/95	4/99	PARO110				
	1.6i 216 Cabrio	109	1590				3/96	6/99	PARO113				
	1.6i 216 DOHC Coupe		1589	D16A8			7/97	6/99	PARO113				
	1.8i 218 Vi		1796	18K4K			10/96	10/99	PARO110				
	1.8i 218		1796				6/97	4/99	PARO110				
	2.0i 220 SLi GSi Hatch		1994	20T4H/ 20M4F			6/91	3/96	PARO112	FP2008			Replaces Nippon Denso / JECS Pump

FPA3A.503.

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
2.0i 220 Turbo	Hatch		1994	20T4G			10/92	11/93	PARO112				
2.0i 220 Turbo	Coupe		1994	20T4G			10/92	3/96	PARO112				
2.0i 220 Turbo	Hatch		1994	20T4G			10/92	11/93		FP2008			Replaces Nippon Denso Pump
2.0i 220 Turbo	Coupe		1994	20T4G			10/92	3/96		FP2012			Replaces Walbro Pump
25													
1.4	16v	83/ 103	1396				11/99		PARO110				
1.6i	16v		1589				11/99		PARO110				
1.8i	16v	115/ 143	1796				11/99	5/01	PARO110				
400													
1.4i	414		1396		Ch 605482->		10/92	2/96	PARO111				
1.4i	414 GSi		1396	14K4F			10/92	10/95	PARO112				Without Level Sensor
1.4i	414 Hatch		1396	14K4F			12/95	6/99		FP2082			
1.4i	414 DOHC		1396	14K4F			5/95	4/99	PARO113	FP2116			
1.6i	416 OHC Hatch		1589	16K4F			5/95	4/99	PARO113				
1.6i	416 Hatch, Saloon		1589	16K4F			12/95	6/99		FP2082			
1.8i	418 Estate		1796	18K4K			3/96	12/96	PARO113				
2.0i	420		1994	20T4H	Ch 605482->		11/91	3/95	PARO112				Without Level Sensor
2.0i	420 Turbo		1994				10/92	10/95	PARO112				

ROVER

400 Cont. — 800

01527 835555

FuelParts^{UK}

Make / Model	Description	BHP	CC	Engine Code	Chassis Number	Model Series	Date From	Date To	Pump Assemblies	Part Number In Tank	Swirl Pot	External Pump	Notes
2.0i 420 Estate		1994		20T4H			6/94	3/96	PARO113				
2.0i 420 Si Hatch		1994		20T4H			11/95	12/99	PARO113				
2.0i 420 Saloon		1994		20T4H			12/95	6/99		FP2082			
2.0i 420 Saloon		1994		20T4H			3/96	12/99	PARO113				
45													
1.4i		1396					1/00		PARO113				
1.6i Saloon		1589					1/00		PARO113				
1.6i Hatch		1589					1/00		PARO113				
1.8i Saloon		1796					1/00		PARO113				
1.8i Hatch		1796					1/00		PARO113				
2.0i V6		1997					12/99		PARO113				
600													
2.0i 620 GSi		1997		F20Z1			4/93	10/99		FP2008			Replaces Nippon Denso / JECS Pump
2.0i 620 SLi		1997		F20Z1			4/93	10/99		FP2069			Replaces Bosch Pump
800													
2.0i 820		1994		20T4H			11/91	10/99		FP2008			Replaces Nippon Denso / JECS Pump
2.0i 820 i Turbo		1994		T16			1/93	10/99		FP2001			Replaces Ac Pump